BRUHAT BANGALORE MAHANAGARA PALIKE

NAME OF WORK: CONSTRUCTION OF MARKET BUILDING AT JP PARK IN WARD NO.17

SITEPHOTOS

BILL TYPE: 4th and Final Bill

Scanned by CamScanner

NAME OF WORK: CONSTRUCTION OF MARKET BUILDING AT JP PARK IN WARD NO.17



Dismantling of front old staircases

Cleaning around the building

AE / JE (P) RRN
AE / JE (P) RRN
R.R. Nagar

CIVIL QUALITY CONSULTANTS & ENGINEERS Bangalore

Scanned by CamScanner

NAME OF WORK: CONSTRUCTION OF MARKET BUILDING AT JP PARK IN WARD NO.17

Dismantling of front old staircases


Tank Bund Road, Near J P Park Gate, 2HM3+3F9, Mathikere, Mohan Kumar Nagar, Mathikere, Bengaluru, Karnataka 560054, India
Bengaluru
Karnataka
India
31°C

Supporting wall for front staircase

AE / JE (P) RRN

AB.E.JE (P) RRN
R.R. Nagar

CIVIL QUALITY CONSULTANTS & ENGINEERS

Scanned by CamScanner

NAME OF WORK: CONSTRUCTION OF MARKET BUILDING AT JP PARK IN WARD NO.17



Supporting wall for front staircase



Front staircase concrete laying

AE / JE (C) RRN

A.E.E (P)
R.R. Nagar

CIVIL QUALITY CONSULTANTS & ENGINEERS Bangalore

Scanned by CamScanner

NAME OF WORK: CONSTRUCTION OF MARKET BUILDING AT JP PARK IN WARD NO.17



Front staircase steel work



Front staircase centering work

AE / JE (P) RRN

A.E.E (P)
R.R. Nagar

CIVIL QUALITY CONSULTANTS & ENGINEERS
Bangalore

Scanned by CamScanner

NAME OF WORK: CONSTRUCTION OF MARKET BUILDING AT JP PARK IN WARD NO.17



Front staircase centering work



Front staircase concreting work

AE / JE (R&RN)

A.E.E (P)
R.R. Nagar

CIVIL QUALITY CONSULTANTS & ENGINEERS Bangalore

Scanned by CamScanner

NAME OF WORK: CONSTRUCTION OF MARKET BUILDING AT JP PARK IN WARD NO.17

Front staircase centering work



AE / JE (P) RRN

A.E.E (P)
R.R. Nagar

CIVIL QUALITY CONSULTANTS & ENGINEERS
Bangalore

Scanned by CamScanner

Front staircase concreting work

NAME OF WORK: CONSTRUCTION OF MARKET BUILDING AT JP PARK IN WARD NO.17



Cleaning of ceiling for putty work

Inside putty work

AE / JE (P) RRN

A.E.E (P)
R.R. Nagar

QUALITY CONSULTANTS & ENGINEERS
Bangalore
CIVIL

Scanned by CamScanner

NAME OF WORK: CONSTRUCTION OF MARKET BUILDING AT JP PARK IN WARD NO.17



Inside putty work

Plastering of external walls

AE / JE (P) RRN

A.E.E (P)
R.R.Nagar

CIVIL QUALITY CONSULTANTS & ENGINEERS Bangalore

Scanned by CamScanner

NAME OF WORK: CONSTRUCTION OF MARKET BUILDING AT JP PARK IN WARD NO.17



Plastering to the inside walls after block work finishing



Plastering work of building

AE / JE (P) RRN

A.E.E (P)
R.R. Nagar

CIVIL QUALITY CONSULTANTS & ENGINEERS
Bangalore

Scanned by CamScanner

NAME OF WORK: CONSTRUCTION OF MARKET BUILDING AT JP PARK IN WARD NO.17



Painting of external walls



Plastering of external walls

AE / JE (P) RRN

A.E.E (P)
R.R.Nagar

CIVIL QUALITY CONSULTANTS & ENGINEERS Bangalore

Scanned by CamScanner

NAME OF WORK: CONSTRUCTION OF MARKET BUILDING AT JP PARK IN WARD NO.17


Tank Bund Road, Near J P Park Gate, 2HM3+3F9, Mathikere, Mohan Kumar Nagar, Mathikere, Bengaluru, Karnataka 560054, India
Bengaluru
Karnataka
India
26°C

Painting of external walls



Painting of external walls

AE / JE (P) RRN

A.E.E (P)
R.R.Nagar

CIVIL QUALITY CONSULTANTS & ENGINEERS Bangalore

Scanned by CamScanner

NAME OF WORK: CONSTRUCTION OF MARKET BUILDING AT JP PARK IN WARD NO.17



Painting of putty walls

Rainwater pipes

AE / JE (P) RRN

A.E.E (P)
R.R. Nagar

CIVIL QUALITY CONSULTANTS & ENGINEERS
Bangalore

Scanned by CamScanner

NAME OF WORK: CONSTRUCTION OF MARKET BUILDING AT JP PARK IN WARD NO.1



Blockwork for walls



AE and EE inspection during work

AE/JE (P) RRN

A.E.E (P)
R.R. Nagar

CIVIL QUALITY CONSULTANTS & ENGINEERS
Bangalore

NAME OF WORK: CONSTRUCTION OF MARKET BUILDING AT JP

Scanned by CamScanner

PARK IN WARD NO.17



Front stair and handrail work

Executive engineer site inspection during work

AE / JE (P) RRN

A.E.E (P)
R.R.Nag

CIVIL QUALITY CONSULTANTS & ENGINEERS
Bangalore

Scanned by CamScanner